



SECTION VIEW

STANDARD TYPICAL SEWER POINT REPAIR



EFFECTIVE: 07/01/23

DETAIL No.

7000.30