



- NOTES:**
1. NO HORIZONTAL ALIGNMENT CHANGE CAN BE MADE WITHIN THIS MANHOLE TYPE. USE ON GRADES OF 10% OR GREATER.
 2. EACH JOINT OF PIPE BETWEEN HIGH VELOCITY MANHOLE & MANHOLE UPGRADE SHALL HAVE A THRUST COLLAR (SEE STANDARD DETAIL 6000.22).



STANDARD HIGH VELOCITY MANHOLE INVERT

DETAIL No.
7000.17

EFFECTIVE: 07/01/22