


SECTION VIEW

STANDARD TYPICAL SEWER POINT REPAIR



EFFECTIVE: 07/01/22

DETAIL No.
7000.30